

FACILITY COMPLIANCE AUDIT REPORT

Division of Waste Management Solid Waste Section

UNIT TYPE:											
Lined MSWLF	LCID	YW	Transfer	X Compost	SLAS	COUNTY: Catawba					
Closed MSWLF	HHW	White goods	Incin	T&P	FIRM	PERMIT NO.: 18-08T					
CDLF	Tire T&P / Collection	Tire Monofill	Industrial Landfill	DEMO	SDTF	FILE TYPE: COMPLIANCE					

Date of Audit: October 28, 2008

Date of Last Audit: July 9, 2008

FACILITY NAME AND ADDRESS:

City of Hickory Transfer Station 1050 1st Avenue SW Hickory, North Carolina 28601

GPS COORDINATES: N: <u>35.73125</u> W: <u>81.35588</u>

FACILITY CONTACT NAME AND PHONE NUMBER:

Mr. John Yvars, Solid Waste Supervisor (828) 323-7439

FACILITY CONTACT ADDRESS:

P.O. Box 398 Hickory, North Carolina 28601

AUDIT PARTICIPANTS:

Charles Gerstell, NCDENR, Solid Waste Section John Yvars, Solid Waste Supervisor

STATUS OF PERMIT:

Permit issued 2/17/05. Renewal date is 2/17/10.

PURPOSE OF AUDIT:

Follow-up audit

NOTICE OF VIOLATION(S):

None

You are hereby advised that, pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Statute or Regulations. For the violation(s) noted here, you may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

FACILITY COMPLIANCE AUDIT REPORT Division of Waste Management Solid Waste Section

Page 2 of 2

STATUS OF PAST NOTED VIOLATIONS:

15A NCAC 13B .0402(3): During a previous inspection performed on July 9, 2008, leachate was observed leaking from two loaded, solid waste transfer trailers and one empty trailer at the facility. Leachate from these trailers was observed flowing into a catch basin that lead directly to the storm sewer system. This leachate was not treated prior to being released from the site into the storm sewer system. Corrective actions have been implemented to prevent further releases of leachate from the site. An additional 6-inch trench drain had been installed at the paved lot south of the facility. This drain ties into the existing drains that lead to the sanitary sewer system. The storm drain mentioned on previous reports had been covered over with asphalt to prevent flow from entering the device. John Yvars stated that plans were to pave the asphalt lot south of the transfer facility to ensure that potential leachate will flow to those drains which lead to the sanitary sewer system. Please continue efforts to complete corrective actions and inform this office when all work has been completed.

15A North Carolina Administrative Code 13B .0105(c): During the previous inspection performed on July 9, 2008, leachate was observed leaking from two loaded, solid waste transfer trailers that were being prepared to be taken to the Catawba County Landfill. Leachate was also observed leaking from an empty trailer at the facility. John Yvars notified the Division that seals had been replaced on all transfer trailers. No liquid was observed leaking from the trailers at the time of inspection.

AREAS OF CONCERN AND COMMENTS:

- 1. This inspection was performed to determine the status of compliance with the Compliance Order with Administrative Penalty issued on August 13, 2008. Please refer to the above comments for a status of compliance efforts.
- 2. Windblown waste was well managed at the time of inspection
- 3. No unacceptable waste streams were observed at the time of inspection.
- 4. A revised Operations Plan has been submitted to the Division and is currently under review.

Please contact me if you have any questions or concerns regarding this audit report.

Charles T. Gerstell

Environmental Senior Specialist

Regional Representative

Phone: (704) 663-1699.

Delivered on : 11/7/08 by	Hand delivery	X	US Mail	Certified No. [_]